

TYX CORPORATION

---

Productivity Enhancement Systems



# PAWS Studio Release Notes

Version 1.39.6  
December 1, 2011

## Table of contents

<b>1</b>	<b>Paws Developer's Studio</b>	<b>3</b>
1.1	Critical Items	3
1.2	Known Limitations	3
1.3	Enhancements	3
1.4	Problem Reports	3
<b>2</b>	<b>Run Time System</b>	<b>4</b>
2.1	Critical Items	4
2.1.1	Unable to return output values from COM NAM	4
2.2	Known Limitations	4
2.3	Enhancements	4
2.4	Problem Reports	4
2.4.1	PR11046(TFS-ID 882) Possible Memory Leak	4

## **1 Paws Developer's Studio**



**Version 1.39.6**

**Release date: December 1, 2011**

**1.1 Critical Items**

**1.2 Known Limitations**

**1.3 Enhancements**

**1.4 Problem Reports**

## 2 Run Time System



**Version 1.39.6**

**Release date: December 1**

### 2.1 Critical Items

#### 2.1.1 Unable to return output values from COM NAM

This release fixes a bug that has been present in 1.39.5 Paws Package only. As a result of this bug, any COM NAM is unable to return any output values to their receiving atlas variables.

### 2.2 Known Limitations

### 2.3 Enhancements

### 2.4 Problem Reports

#### 2.4.1 PR11046(TFS-ID 882) Possible Memory Leak

A partial resolution of this problem report had been generating the critical item described above. This version of RTS resolves both this problem report and the critical issue released with 1.39.5