

TYX CORPORATION

Productivity Enhancement Systems

---



# PAWS Studio Release Notes

Version 1.37.4  
March 25, 2009

# Table of contents

|          |                                                                   |          |
|----------|-------------------------------------------------------------------|----------|
| <b>1</b> | <b>Paws Developer's Studio</b>                                    | <b>3</b> |
| 1.1      | Critical Items                                                    | 3        |
| 1.2      | Known Limitations                                                 | 3        |
| 1.3      | Enhancements                                                      | 3        |
| 1.3.1    | Improved Paws Developer's Studio Editor 'Find Next' functionality | 3        |
| 1.4      | Problem Reports                                                   | 3        |
| <b>2</b> | <b>Run Time System</b>                                            | <b>4</b> |
| 2.1      | Critical Items                                                    | 4        |
| 2.2      | Known Limitations                                                 | 4        |
| 2.3      | Enhancements                                                      | 4        |
| 2.4      | Problem Reports                                                   | 4        |
| 2.4.1    | PR09019                                                           | 4        |

# 1 Paws Developer's Studio



Version 1.37.4

Release date: March 25, 2009


## 1.1 Critical Items

## 1.2 Known Limitations

## 1.3 Enhancements

### 1.3.1 Improved Paws Developer's Studio Editor 'Find Next' functionality

'Find Next' functionality of the Paws Developer's Studio editor is improved to notify the user that the starting point of the 'Find' has been reached when one entire traversal of the file search has completed.



## 1.4 Problem Reports

## 2 Run Time System



Version 1.37.4

Release date: March 25, 2009

### 2.1 Critical Items

### 2.2 Known Limitations

### 2.3 Enhancements

### 2.4 Problem Reports

#### 2.4.1 PR09019

Apart from compiler changes the PR needed an updated size calculation for 'QTYPE' indirect path connection variable for the fix.